

Activity 1

Figure below shows an arrangement for measuring the dimension L on a block using a dial gage. If the dial gage gives a reading of 5.212 mm, calculate the error in the measurement. Given that angle $\theta = 5^\circ$.

